

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K010000	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 03/13/13</p> <p>Facility Number: 000038 Provider Number: 155095 AIM Number: 100274830</p> <p>Surveyor: Amy Kelley, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, Heritage Park was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, areas open to the corridors and hard wired smoke detectors in the resident rooms on the 200 hall. The remaining</p>		K010000				

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/27/2013
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>resident rooms have battery operated smoke detectors. The facility has a capacity of 180 and had a census of 160 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered. All areas providing facility services were sprinklered, except one shed used for the maintenance office and general storage and an additional shed used for maintenance storage.</p> <p>Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 03/18/13.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K010018 SS=E	<p>NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1¾ inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3</p> <p>Roller latches are prohibited by CMS regulations in all health care facilities. Based on observation and interview, the facility failed to ensure the corridor doors to 1 of 1 Heritage conference rooms and 1 of 1 employee break rooms would close and latch into the door frame. This deficient practice could affect any residents in the Heritage conference room which has enough chairs to seat 25 residents and staff in the employee break room.</p> <p>Findings include:</p> <p>a. Based on observation with the Maintenance Supervisor on 03/13/13 at 1:20 p.m., one of the double corridor doors to Heritage conference room could be manually latched into the door frame, but it would not latch into the door frame</p>			K010018	<p>1. The positive latching hardware for the employee break room door was immediately repaired. We have hired Moss Engineering to assist us with adding positive latching hardware to the Heritage Room door. 2. No residents were affected by this alleged deficient practice 3. Reviewed all doors in the facility to assure proper closures are in place, none found. 4. Maintenance Director will approve and supervise all new doors placed in the facility to assure they meet the regulations.</p>		03/26/2013

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/27/2013
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>automatically when closed. The remaining door would latch into the stationary door once it was fastened manually into the door frame. The first door lacked positive latching hardware. This was acknowledged by the Maintenance Supervisor at the time of observation.</p> <p>b. Based on observation with the Maintenance Supervisor on 03/13/13 at 2:20 p.m., the corridor door to the employee break room was held closed with a magnet that would release upon activation of the fire alarm. The positive latching hardware did not work properly. Once the magnetic disengaged the door could be pushed open. This was confirmed by the Maintenance Supervisor during the test of the fire alarm system at 3:45 p.m. on 03/13/13.</p> <p>3.1-19(b)</p>						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K010027 SS=E	<p>NFPA 101 LIFE SAFETY CODE STANDARD Door openings in smoke barriers have at least a 20-minute fire protection rating or are at least 1¾-inch thick solid bonded wood core. Non-rated protective plates that do not exceed 48 inches from the bottom of the door are permitted. Horizontal sliding doors comply with 7.2.1.14. Doors are self-closing or automatic closing in accordance with 19.2.2.2.6. Swinging doors are not required to swing with egress and positive latching is not required. 19.3.7.5, 19.3.7.6, 19.3.7.7 Based on observation and interview, the facility failed to ensure 1 of 11 sets of smoke barrier doors would restrict the movement of smoke for at least 20 minutes. LSC 19.3.7.6 requires doors in smoke barriers shall comply with LSC Section 8.3.4. LSC 8.3.4.1 requires doors in a smoke barrier shall close the opening leaving only the minimum clearance necessary for proper operation which is defined as 1/8 inch. The deficient practice could affect 2 of 12 smoke compartments.</p> <p>Finding include:</p> <p>Based on observation with the Maintenance Supervisor on 03/13/13 at 2:30 p.m., the coordinating device at the smoke barrier doors entering the 500 hall at the library failed to function properly leaving a four inch gap between the doors when closed. This was confirmed by the</p>			K010027	<p>1. The door in question was immediately readjusted.2. No residents were found to have been affected by the alleged deficient practice.3. Weekly tests of all fire doors will be completed for 4 weeks to assure proper closure, then monthly thereafter. Results will be reported to the Executive Director and governing CQI committee.4. The Maintenance Supervisor is responsible for rounds, reporting to ED and CQI Committee. Maintenance Supervisor is also, responsible to assure any noted issues are immediately corrected.</p>		03/22/2013

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/27/2013

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	Maintenance Supervisor at the time of observation. 3.1-19(b)						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K010044 SS=E	<p>NFPA 101 LIFE SAFETY CODE STANDARD Horizontal exits, if used, are in accordance with 7.2.4. 19.2.2.5</p> <p>Based on observation and interview, the facility failed to ensure 1 of 2 fire door sets was arranged to automatically close and latch. LSC 19.2.2.5 requires horizontal exits to be in accordance with 7.2.4 and 7.2.4.3.8 requires fire doors to be self closing or automatic closing in accordance with 7.2.1.8. In addition NFPA 80, Standard for Fire Doors and Windows at 2-1.4.1 requires all closing mechanisms shall be adjusted to overcome fire resistance of the latch mechanism so positive latching is achieved on each door operation. This deficient practice could affect any of the 48 residents on the 100 and 200 halls.</p> <p>Findings include:</p> <p>Based on observation with the Maintenance Supervisor on 03/13/13 at 1:45 p.m., the west fire door on the fire door set entering the 200 hall failed to latch into the frame. Based on an interview with the Maintenance Supervisor at the time of observation, these doors were confirmed to be one hour fire doors and the west door is warped preventing it from latching into the door frame.</p>		K010044	<p>1. The west fire door on the fire door set entering 200 hall was immediately adjusted by Maintenance staff. In addition, we have hired an outside contractor to assess the warping, and correct or replace door, if needed.2. No resident was found to have been harmed by the alleged deficient practice.3. Maintenance Supervisor is responsible for assuring the proper functioning of fire doors. Fire doors will be checked weekly for 4 weeks and then monthly. Maintenance Supervisor will immediately address/correct any issues.4. Maintenance Supervisor will report all findings to the Executive Director and the governing CQI committee monthly.</p>		03/29/2013	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/27/2013

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	3.1-19(b)						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K010064 SS=D	<p>NFPA 101 LIFE SAFETY CODE STANDARD Portable fire extinguishers are provided in all health care occupancies in accordance with 9.7.4.1. 19.3.5.6, NFPA 10</p> <p>Based on observation and interview, the facility failed to ensure 1 of 1 kitchen electrical room fire extinguishers was provided maintenance when the gauge on the fire extinguisher indicated it needed recharging. NFPA 10, Standard for Portable Fire Extinguishers, in Section 4-4.1 requires fire extinguishers to be subjected to maintenance no more than one year apart or when specifically indicated by inspection. This deficient practice was not in a resident care area but could affect kitchen staff in the event of an emergency.</p> <p>Findings include:</p> <p>Based on an observation with the Maintenance Supervisor on 03/13/13 at 3:20 p.m., the gauge on the portable fire extinguisher located in the kitchen electrical room indicated the extinguisher needed to be recharged. This was acknowledged by the Maintenance Supervisor at the time of observation.</p> <p>3.1-19(b)</p>		K010064	<p>1. The fire extinguisher was immediately replaced.2. No residents were found to be affected by the alleged deficient practice.3. A detailed diagram of all fire extinguishers in the building has been created, this tool will be used to assure that every extinguisher is checked during monthly rounds.4. The Maintenance Supervisor is responsible for rounding and for reporting findings to the Executive Director and governing CQI committee. He is also responsible for assuring any issues found are corrected.</p>		03/29/2013	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/27/2013

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K010144 SS=F	<p>NFPA 101 LIFE SAFETY CODE STANDARD Generators are inspected weekly and exercised under load for 30 minutes per month in accordance with NFPA 99. 3.4.4.1.</p> <p>Based on record review and interview, the facility failed to ensure 1 of 1 emergency generators could provide electrical power to the facility within 10 seconds of the loss of normal electrical power. LSC 7.9.2.3 and NFPA 99, Health Care Facilities, 3-4.1.1.8 requires the generator set shall have sufficient capacity to pick up the load and meet the minimum frequency and voltage stability requirements of the emergency system within 10 seconds after loss of normal power. This deficient practice affects all occupants.</p> <p>Findings include:</p> <p>Based on review of the "Emergency Generator - Weekly Exercise/Monthly Load Test Log" with the Maintenance Supervisor on 03/13/13 at 12:48 p.m., the monthly load test record indicated the transfer of power from the main source to the emergency generator took fifteen seconds in October and December of 2012 and February of 2013. This was confirmed by the Maintenance Supervisor at the time of record review.</p>		K010144	<p>1. We have hired WW Williams to provide a Load Bank, cabling, hook up and disconnection of Load Bank, testing will be for 2 hours and will be performed in accordance with the 2010 NFPA 110 Regulation 8.4.9.2. No residents were found to have been affected by the alleged deficient practice.3. Maintenance Supervisor will assure testing and changes are completed by WW Williams.4. Maintenance Supervisor will notify the Executive Director and governing CQI committee monthly of results of emergency generator testing. He will be responsible for assuring the transfer of power in 10 seconds or less and taking corrective action, if needed.</p>		03/29/2013	

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/27/2013

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155095		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 03/13/2013	
NAME OF PROVIDER OR SUPPLIER HERITAGE PARK				STREET ADDRESS, CITY, STATE, ZIP CODE 2001 HOBSON RD FORT WAYNE, IN 46805			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	3.1-19(b)						